




Figura 8.34. Pérdida por salida.

TABLA 8.19. Coeficientes de pérdida por salida

$\frac{A_2}{A_1}$	K
0.1	0.83
0.2	0.84
0.3	0.85
0.4	0.87
0.5	0.88
0.6	0.90
0.7	0.92
0.8	0.94
0.9	0.965
1	1.0